



TO: David Helbock
1525 Wilson Blvd, Suite 225
Arlington, VA 22209

FROM: Matt Arnold on behalf of the FICAM Testing Program

DATE: 8/08/2022

RE: **Updated Approval Letter for Listing on the GSA APL**

Office of Management and Budget (OMB) issued M-19-17 that requires Federal Agencies to procure only qualified products and services listed on the GSA Approved Products List (APL) when implementing HSPD-12 into their environment. Procurement of approved products and services facilitates the government-wide objective of a federated and interoperable ICAM segment architecture, and ensures compliance, consistency and alignment of commercially-available products and services with the requirements and functional needs of government ICAM implementer.

Accordingly, the FIPS 201 Evaluation Program (Program) is very pleased to inform you that the following product/service has passed testing against all applicable Testing Requirements. Please see the attached document that summarizes the specific parameters of the approval (e.g., product/service profile, what your product/service was tested with). Your product/service will now be listed on the APL as shown below. If there are any errors in the listing information, please notify me within five (5) business days of receiving this letter.

Approval Authorization Letter

1 Category-PACS Infrastructure (APL #10013)

1.1 APL Certification Number

- (APL #10013)
 - Identiv Velocity Security Management System
 - Identiv Hirsch MX controllers MX1 / MX2 / MX4 / MX8
 - Identiv Secure Network Interface Board v3 (SNIB3)

1.2 Product/Service Information

| | |
|------------------------------------|-------------------------------------|
| Organization Name: | Identiv |
| Name of Product or Service: | Velocity Security Management System |
| Part Number: | VELFED |
| Hardware Version: | N/A |
| Software Version: | 3.8.4 |
| Firmware Version: | N/A |

| | |
|------------------------------------|-----------------------|
| Organization Name: | Identiv |
| Name of Product or Service: | Hirsch MX controllers |
| Part Number: | MX1 / MX2 / MX4 / MX8 |
| Hardware Version: | 7 |
| Software Version: | N/A |
| Firmware Version: | 8.2.01.28 |

| | |
|------------------------------------|---|
| Organization Name: | Identiv |
| Name of Product or Service: | Secure Network Interface Board v3 (SNIB3) |
| Part Number: | SNIB3 |
| Hardware Version: | N/A |
| Software Version: | N/A |
| Firmware Version: | 04.00.0088 |

1.3 Document History

| Status | Date | Comments |
|----------|-----------|---|
| Approved | 5/27/2014 | Final Approval Date for APL# 10013: Velocity Software Version 3.5 SP1 Build 145 / Hirsch Panel Software Version 7.5.08, Firmware Version 5.99, Hardware Version SNIB2 |
| Update | 4/15/2015 | Added RPKCLB40 Reader APL #10026, and Identiv uTrust TS reader (CAK) Mullion APL #10042 |
| Update | 7/7/2015 | Added RKCLB40 Reader APL#10052 |
| Update | 7/25/2015 | Final Approval Date for uTrust Readers APL #10057, 10058, 10059 |
| Update | 6/29/2016 | Final Approval Date of Upgrade of Velocity Software Version to 3.5 SP2.1 Build 30-174 |
| Update | 6/29/2016 | Final Approval Date of Upgrade of Hirsch Panel Software Version 7.5.31, Firmware Version 1.07, Hardware Version SNIB3 |
| Update | 6/29/2016 | Added Product Series for Hirsch Panel, available in 2, 4 or 8 doors |
| Update | 2/3/2017 | Updated to reflect new part numbering scheme for CSRP readers (PACS Topology 13.01). |
| Update | 5/14/2020 | Update Velocity Software 3.7 SP2, Hardware Firmware (7.6.43 and 2.04.1038), and HID pivCLASS 5.11.0.0 |
| Update | 5/9/2021 | Update to Velocity Software 3.8.2, Hardware version and HID pivCLASS. |
| Update | 9/21/2021 | Update to Velocity software 3.8.3 and HID version to 5.17.2.0 |
| Update | 8/8/2022 | Update to Velocity software 3.8.4 and HID version to 5.20 |

1.4 Restrictions:

This product has been tested and approved as a component of a fully compliant FICAM Solution. The end-to-end solution components used to test the FICAM compliance of the approved solution are listed below.

- Validation System (APL# **10014**)
 - pivCLASS Registration Engine (Hirsch-Identiv Velocity)
 - pivCLASS Certificate Manager
 - pivCLASS Reader Services

- pivCLASS IDPublisher
- pivCLASS Authentication Module
- PIV Reader
 - pivCLASS RP40 Contactless Reader (APL#**10003**)
 - pivCLASS RK40 Contactless Reader + PIN (APL# **10004**)
 - pivCLASS RPK40 Contactless Reader + PIN (APL# **10005**)
 - pivCLASS R40 Contactless Reader (APL# **10006**)
 - pivCLASS RKCL40 Contact/Contactless Reader with PIN (APL# **10007**)
 - pivCLASS RPKCL40 Contact/Contactless Reader with PIN (APL# **10008**)
 - pivCLASS RPKCLB40 Contact/Contactless Reader with PIN & BIO (APL# **10026**)
 - pivCLASS RKCLB40 Contact/Contactless Reader with PIN & BIO (APL# **10052**)
 - pivCLASS R10 Contactless Reader (APL# **10085**)

Approval of the above product/service indicates your cooperation with the Program and successful testing against a rigorous, comprehensive set of functional requirements derived from government-wide specifications. Testing included positive and negative test cases, and threat vectors.

Given the strategic government-wide importance of the APL, the scope and extent of testing performed on your product/service, and the rigor of that testing, the Program would like to acknowledge the noteworthiness of the approval and listing. Your product/service will now be available to all Federal Agencies for procurement.

Please note that continued listing on the APL requires ongoing conformance to all applicable requirements, including requirements added or amended over time. A listed product/service can become non-conformant for various reasons including but not limited to:

- Failure to pass testing against new and revised requirements before the effective date of the new/revised requirements.
- Problems discovered in your listed product/service (or class of product/service) are not addressed within time frames specified by the Program.

Refer to applicable Agreements and Program documents for specific details regarding ongoing compliance including severity levels and remediation time frames. Listed products and services that fall out of conformance will be removed from the APL and added to the Removed Products List (RPL).

If you have any questions, please feel free to contact me.

Matthew Arnold
GSA OGP
(703) 254-6750
Matthew.Arnold@gsa.gov